

Figure1. Return Loss(S11)




Figure2. Port Isolation






Figure3. Insertion Loss(S21)




Figure4. Insertion Loss(S31)